# Accessibility Survey



# City of Sierra Madre Library

440 W Sierra Madre Boulevard Sierra Madre, CA 91024

Date of Inspection 5/31/2016

Prepared By Disability Access Consultants (800) 743-7067

## Parking - Exterior : Parking Lot , Parking Space

Parking Lot Accessible Space At Rear Parking

## Finding

The surface of the accessible parking space has a slope greater than allowed.

**On-Site Finding** 6.80 percent

## Recommendation

Pave the parking lot to provide a level surface.

Recommendation Up to 2.08 percent

## **Costing Info (Estimated)**

Repave surface to correct slope and \$3,800 re-stripe

Code Reference ADA 502, 502.4, CA 11B-502.4

Record Number 168153

Parking Lot , Parking Space : Parking Space Slope



## Parking - Exterior : Parking Lot , Parking Space

Parking Lot

Accessible Space At Rear Parking

## Finding

There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.

On-Site Finding No Access Aisle

#### Recommendation

Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Paint ground markings and install a \$370 post mounted sign

Code Reference ADA 502, 502.3.4, 502.3,CA 11B-502.2

Record Number 168154

## Parking - Exterior : Parking Lot, Warning Signage

Parking Lot Accessible Space At Rear Parking

#### Finding

There is no \$250.00 fine sign at the parking space.

**On-Site Finding** Not Found

## **Recommendation** Provide a \$250.00 fine sign at the parking space.

Recommendation See Recommendation

**Costing Info (Estimated)** Install signage

\$300

Code Reference CA 11B-502.8

Record Number 168155

Disability Access Consultants (DAC) 1-800-743-7067

Parking Lot , Parking Space : No Access Aisle

Parking Lot , Warning Signage : Parking Lot Warnings





## Parking - Exterior : Parking Lot , Parking Space

## Parking Lot

Next To Main Entrance, Left Accessible Space

## Finding

The pavement marking at the designated accessible parking space is not centered and aligned with the end of the space.

#### On-Site Finding Not Visible

#### Recommendation

Provide a compliant pavement marking at the designated accessible parking space.

Recommendation See Recommendation

## Costing Info (Estimated)

Stripe an access aisle \$220

Code Reference CA 11B-502.6.4

Record Number 168160

## Parking - Exterior : Parking Lot , Parking Space

## **Parking Lot**

Next To Main Entrance, Left Accessible Space

#### Finding

There is no additional signage marked "van accessible" at the van accessible parking space.

**On-Site Finding** None Found

#### Recommendation

Van accessible parking spaces shall provide additional signage that states "van accessible" .

Recommendation See Recommendation

## Costing Info (Estimated)

Install post mounted sign		\$250
Code Reference	ADA 502, 502.6	
Record Number	168161	

Parking Lot , Parking Space : Parking Space ISA not Visible



Parking Lot , Parking Space : No Van Accessible Signage



## Parking - Exterior : Parking Lot , Parking Space

## Parking Lot

Next To Main Entrance, Left Accessible Space

## Finding

The access aisle does not meet the minimum required width.

**On-Site Finding** 53.00 inches

## Recommendation

Re-stripe the access aisle to meet the minimum required width and length for the space type.

Recommendation At least 96.00 inches

## **Costing Info (Estimated)**

Stripe an access aisle \$250

Code Reference CA 11B-502.2

Record Number 168162

## Parking - Exterior : Parking Lot , Parking Space

## Parking Lot

Next To Main Entrance, Left Accessible Space

## Finding

The access aisle exceeds maximum slope.

**On-Site Finding** 4.40 percent

## Recommendation

Pave the parking lot to provide a level surface.

Recommendation Up to 2.08 percent

## Costing Info (Estimated)

Repave surface to correct slope and \$3,800 re-stripe

**Code Reference** ADA 502, 502.4,CA 11B-502.4

Record Number 168163





Parking Lot , Parking Space : Access Aisle Slope



## Parking - Exterior : Parking Lot , Parking Space

## Parking Lot

Next To Main Entrance, Left Accessible Space

## Finding

The access aisle does not contain the wording "No Parking" painted on surface within the access aisle in white letters.

**On-Site Finding** None Found

#### Recommendation

Paint "NO PARKING" in 12 inch white letters.

Recommendation See Recommendation

## Costing Info (Estimated)

Stripe an access aisle \$250

Code Reference CA 11B-502.3.3

Record Number 168164

## Parking - Exterior : Parking Lot , Parking Space

## **Parking Lot**

Next To Main Entrance, Left Accessible Space

## Finding

The accessible parking space outline is faded, damaged, missing or otherwise not viewable.

**On-Site Finding** Faded or Damaged

#### Recommendation

Re-stripe the existing parking space marked as accessible to define the width of the space.

Recommendation See Recommendation

## Costing Info (Estimated)

Re-stripe existing	parking space	\$350
Code Reference	ADA 502, 502	.2,CA 11B-502.2

Record Number 168157

Parking Lot , Parking Space : Access Aisle Does Not Say "No Parking"



Parking Lot , Parking Space : Outline is Faded, Damaged or Missing



## Parking - Exterior : Parking Lot , Parking Space

**Parking Lot** Next To Main Entrance, Left Accessible Space

## Finding

The surface of the accessible parking space has a slope greater than allowed.

On-Site Finding 3.70 percent

#### Recommendation

Pave the parking lot to provide a level surface.

Recommendation Up to 2.08 percent

## **Costing Info (Estimated)**

Repave surface to correct slope and \$3,800 re-stripe

Code Reference ADA 502, 502.4, CA 11B-502.4

Record Number 168158

## Parking - Exterior : Parking Lot, Warning Signage

## Parking Lot

Next To Main Entrance, Left Accessible Space

## Finding

There is no \$250.00 fine sign at the parking space.

**On-Site Finding** Not Found

#### Recommendation

Provide a \$250.00 fine sign at the parking space.

Recommendation See Recommendation

## Costing Info (Estimated)

Install signage		\$300
Code Reference	CA 11B-502.8	
Record Number	168159	

Parking Lot , Parking Space : Parking Space Slope



Parking Lot , Warning Signage : Parking Lot Warnings



Disability Access Consultants (DAC) 1-800-743-7067

## Parking - Exterior : Parking Lot , Parking Space

## Parking Lot

Next To Main Entrance, Right Accessible Space

## Finding

The pavement marking at the designated accessible parking space is not centered and aligned with the end of the space.

#### **On-Site Finding** Not Visible

#### Recommendation

Provide a compliant pavement marking at the designated accessible parking space.

Recommendation See Recommendation

## Costing Info (Estimated)

Stripe an access aisle \$220

Code Reference CA 11B-502.6.4

Record Number 168152

## Parking - Exterior : Parking Lot , Parking Space

## **Parking Lot**

Next To Main Entrance, Right Accessible Space

#### Finding

The accessible parking space outline is faded, damaged, missing or otherwise not viewable.

On-Site Finding Faded or Damaged

#### Recommendation

Re-stripe the existing parking space marked as accessible to define the width of the space.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Re-stripe existing	parking spa	ce \$	350
Code Reference	ADA 502,	502.2,CA	11B-502.2

Record Number 168149

 $\ensuremath{\mathsf{Parking}}$  Lot ,  $\ensuremath{\mathsf{Parking}}$  Space :  $\ensuremath{\mathsf{Parking}}$  Space ISA not Visible



Parking Lot , Parking Space : Outline is Faded, Damaged or Missing



## Parking - Exterior : Parking Lot , Parking Space

## **Parking Lot**

Next To Main Entrance, Right Accessible Space

## Finding

The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.

**On-Site Finding** None Found

## Recommendation

Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel to the facility for which it serves and shall coincide with the primary route and primary entrances used by the general public.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Stripe vehicle space and access aisle, \$1,379 install pole mounted signage, install concrete curb cut

Code Reference ADA 502, 208, 208.3

Record Number 168150

Parking Lot , Parking Space : Space is Not on Accessible Route



## Parking - Exterior : Parking Lot , Warning Signage

\$300

**Parking Lot** Next To Main Entrance, Right Accessible Space

## Finding

There is no \$250.00 fine sign at the parking space.

**On-Site Finding** Not Found

## Recommendation

Provide a \$250.00 fine sign at the parking space.

Recommendation See Recommendation

Costing Info (Estimated) Install signage Code Reference CA 11B-502.8

Record Number 168151

Parking Lot , Warning Signage : Parking Lot Warnings



## Parking - Exterior : Parking Lot , Warning Signage

## Parking Lot

Warning Sign At Mariposa

## Finding

There is no warning signage posted regarding unauthorized use of accessible parking spaces in the parking lot.

## **On-Site Finding** Not Found

#### Recommendation

Post a sign in a conspicuous place to the entrance of the parking lot, or immediately adjacent to and visible from each accessible parking space. The warning sign shall measure at least 17 inches by 22 inches in size and consist of lettering at least 1 inch in height that clearly and conspicuously states the following; "Unauthorized vehicles parked in designated accessible spaces not displaying distinguishing placards or license plates issued for persons with disabilities will be towed away at owner's expense. Towed vehicles may be reclaimed at \_\_\_\_\_ or by telephoning \_\_\_\_\_ ." Fill in the blank spaces with appropriate information as a permanent part of the sign and maintain the currency of the information.

Recommendation See Recommendation

## Costing Info (Estimated)

Install post mounted sign\$250Code ReferenceCA 11B-502.8

Record Number 168165

Parking Lot , Warning Signage : No Parking Lot Warning Sign



## Parking - Exterior : Parking Lot , Warning Signage

## **Parking Lot**

Warning Sign At Sierra Madre Boulevard

## Finding

There is no warning signage posted regarding unauthorized use of accessible parking spaces in the parking lot.

## **On-Site Finding** Not Found

#### Recommendation

Post a sign in a conspicuous place to the entrance of the parking lot, or immediately adjacent to and visible from each accessible parking space. The warning sign shall measure at least 17 inches by 22 inches in size and consist of lettering at least 1 inch in height that clearly and conspicuously states the following; "Unauthorized vehicles parked in designated accessible spaces not displaying distinguishing placards or license plates issued for persons with disabilities will be towed away at owner's expense. Towed vehicles may be reclaimed at \_\_\_\_\_ or by telephoning \_\_\_\_\_ ." Fill in the blank spaces with appropriate information as a permanent part of the sign and maintain the currency of the information.

Recommendation See Recommendation

## Costing Info (Estimated)

Install post mounted sign\$250Code ReferenceCA 11B-502.8

Record Number 168166

Parking Lot , Warning Signage : No Parking Lot Warning Sign



## Curb Ramps - Exterior : Curb Ramp

## **Curb Ramp At The Accessible Parking Next To The Main Entrance**

Curb Ramp : No Detectable Warnings

## Finding

The curb ramp does not provide a detectable warning surface which includes truncated domes.

**On-Site Finding** Not Found

## Recommendation

Provide compliant detectable warnings to surface.

Recommendation See Recommendation

## Costing Info (Estimated)

Provide detectable warning to \$248 surface Code Reference CA 11B-406.5.12

Record Number 168090

## Curb Ramps - Exterior : Curb Ramp

**Curb Ramp At The Accessible Parking Next To The Main Entrance** 

# Curb Ramp : Parallel Curb Ramp Left Side Slope

The running slope is greater than allowed.

On-Site Finding 13.30 percent

## Recommendation

Finding

Provide a compliant curb ramp.

Recommendation Up to 8.33 percent

## **Costing Info (Estimated)**

Install curb ramp	\$1,300
Code Reference	ADA 406.1, 405.2,CA 11B-406





## Curb Ramps - Exterior : Curb Ramp

## **Curb Ramp At The Accessible Parking Next To The Main Entrance**

#### Finding

The cross slope is greater than allowed.

On-Site Finding 2.70 percent

#### Recommendation

Provide a compliant curb ramp.

Recommendation Up to 2.08 percent

## Costing Info (Estimated)

Install curb ramp \$1,300 Code Reference ADA 406.1, 405.3,CA 11B-406.5.7

Record Number 168092

## Curb Ramps - Exterior : Curb Ramp

Curb Ramp : Parallel Curb Ramp Left Side Cross Slope



## **Curb Ramp At The Accessible Parking Next To The Main Entrance**

# Curb Ramp : Parallel Curb Ramp Right Side Width

## Finding

The width of the curb ramp is less than required.

On-Site Finding 47.25 inches

#### Recommendation

Install curb ramp

Provide a compliant curb ramp.

Recommendation At least 48.00 inches

## **Costing Info (Estimated)**

\$1,300

**Code Reference** ADA 406.1,CA 11B-406.5.2,CA 11B-406



## Curb Ramps - Exterior : Curb Ramp

## **Curb Ramp At The Accessible Parking Next To The Main Entrance**

## Finding

The running slope is greater than allowed.

**On-Site Finding** 10.00 percent

#### Recommendation

Provide a compliant curb ramp.


Recommendation Up to 8.33 percent

Costing Info (Estimated)

Install curb ramp \$1,300

**Code Reference** ADA 406.1, 405.2, CA 11B-406

Record Number 168094





## Curb Ramps - Exterior : Curb Ramp , Landings and Transitions

Curb Ramp At The Accessible Parking Next To The Main Entrance Bottom Landing

Curb Ramp , Landings and Transitions : Bottom Landing Slope

## Finding

The slope at the bottom landing is greater than allowed.

On-Site Finding 3.30 percent

## Recommendation

Provide a compliant bottom landing that does not exceed the maximum slope requirements.

Recommendation Up to 2.08 percent

## Costing Info (Estimated)

Provide compliant landing	\$240
---------------------------	-------

**Code Reference** ADA 402, 406.4, 406.2, 403.3, 406.1,CA 11B-406.5.3



## Path of Travel - Exterior : Path Of Travel , Vertical Hazards

Around Benches Next To Main Entrance Tree Limb

## Finding

The vertical clearance height is less than required.

**On-Site Finding** 76.00 inches

## Recommendation

Provide recommended vertical clearance.

Recommendation At least 80.00 inches

## **Costing Info (Estimated)**

Provide recommended clearance \$108 Code Reference ADA 307, 307.4,CA 11B-307.4

Record Number 168073

Path Of Travel , Vertical Hazards : Protruding Objects - Vertical Clearance



## Path of Travel - Exterior : Path Of Travel , Walking Surfaces

Around Benches Next To Main Entrance Exterior Walkway

#### Finding

There are slopes greater than allowed maximum slope on the primary path of travel.

On-Site Finding 8.40 percent for 3.00 feet

## Recommendation

Install pathway

Provide compliant sidewalk.

Recommendation Up to 5.00 percent

## Costing Info (Estimated)

\$3,600

**Code Reference** ADA 402, 403.3,CA 11B-403.3,CA 11B-402

Record Number 168072

Path Of Travel , Walking Surfaces : Walking Surface Slope



## Path of Travel - Exterior : Path Of Travel , Walking Surfaces

## From Rear Parking Accessible Space To Main Entrance Change In Level

## Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.62 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

## **Costing Info (Estimated)**

Provide smooth surface \$300

Code Reference ADA 303, 403.4, 303.2,CA 11B-303,CA 11B-403.4

Record Number 168070





## Path of Travel - Exterior : Path Of Travel, Vehicular Traffic

From Rear Parking Accessible Space To Main Entrance Sidewalk Adjoins Parking Space

#### Finding

The pedestrian route adjoins vehicular traffic.

**On-Site Finding** None Found

#### Recommendation

Provide detectable warnings.

Recommendation See Recommendation

## Costing Info (Estimated)

Install detectable v	varnings	\$144
Code Reference	ADA 705,CA	11B-247.1.2.5
Record Number	217521	

Path Of Travel , Vehicular Traffic  $\ : \ No \ Detectable \ Warnings$ 



## Path of Travel - Exterior : Path Of Travel , Vertical Hazards

From Rear Parking Accessible Space To Main Entrance Tree Limb

## Finding

The vertical clearance height is less than required.

**On-Site Finding** 37.00 inches

## Recommendation

Provide recommended vertical clearance.

Recommendation At least 80.00 inches

## **Costing Info (Estimated)**

Provide recommended clearance \$108 Code Reference ADA 307, 307.4,CA 11B-307.4

Record Number 168071





## Path of Travel - Exterior : Path Of Travel , Walking Surfaces

## From Rear Parking Accessible Space To Main Entrance Exterior Walkway

#### Finding

There are slopes greater than allowed maximum slope on the primary path of travel.

**On-Site Finding** 10.40 percent for 85.00 feet

## Recommendation

Install pathway

Provide compliant sidewalk.

Recommendation Up to 5.00 percent

## Costing Info (Estimated)

\$3,600

**Code Reference** ADA 402, 403.3,CA 11B-403.3,CA 11B-402

Record Number 168067

Path Of Travel , Walking Surfaces : Walking Surface Slope



## Path of Travel - Exterior : Path Of Travel , Walking Surfaces

## From Rear Parking Accessible Space To Main Entrance Exterior Walkway

## Finding

There are cross slopes greater than allowed on the primary path of travel.

**On-Site Finding** 3.60 percent for 65.00 feet

## Recommendation

Provide compliant sidewalk.

Recommendation Up to 2.08 percent

## Costing Info (Estimated)

Install pathway \$3,600 Code Reference ADA 402, 403.3,CA 11B-403.3

Record Number 168068





## Path of Travel - Exterior : Path Of Travel , Walking Surfaces

## From Rear Parking Accessible Space To Main Entrance Exterior Walkway

## Finding

The width of the path of travel is insufficient.

**On-Site Finding** 46.37 inches

## Recommendation

Widen the primary path of travel to provide the correct width.

Recommendation At least 48.00 inches

## Costing Info (Estimated)

Widen pathway			\$3,500
Code Reference	ADA 210	504	403 5 1 CA

Code Reference ADA 210, 504, 403.5.1,CA 11B-403.5.1

Record Number 168069

Path Of Travel , Walking Surfaces : Sidewalk Width



## Path of Travel - Exterior : Path Of Travel , Walking Surfaces

## From The Accessible Spaces To Main Entrance Exterior Walkway

## Finding

The width of the path of travel is insufficient.

**On-Site Finding** 47.50 inches

#### Recommendation

Widen the primary path of travel to provide the correct width.

Recommendation At least 48.00 inches

## Costing Info (Estimated)

Widen pathway	\$3,500
Code Reference	ADA 210, 504, 403.5.1,CA
	11B-403.5.1

Record Number 168120

Path Of Travel , Walking Surfaces : Sidewalk Width



## Path of Travel - Exterior : Path Of Travel , Vertical Hazards

From The Public Right Of Way Tree Limb

## Finding

The vertical clearance height is less than required.

**On-Site Finding** 77.00 inches

#### Recommendation

Provide recommended vertical clearance.

Recommendation At least 80.00 inches

## **Costing Info (Estimated)**

Provide recommended clearance \$108 **Code Reference** ADA 307, 307.4,CA 11B-307.4 **Record Number** 168147 Path Of Travel , Vertical Hazards : Protruding Objects - Vertical Clearance



## Path of Travel - Exterior : Path Of Travel , Walking Surfaces

From The Public Right Of Way Exterior Walkway

## Finding

There are slopes greater than allowed maximum slope on the primary path of travel.

**On-Site Finding** 5.70 percent

#### Recommendation

Provide compliant sidewalk.

Recommendation Up to 5.00 percent

#### **Costing Info (Estimated)**

Install pathway \$3,600 **Code Reference** ADA 402, 403.3,CA 11B-403.3,CA 11B-402

Record Number 168146

## Stairs - Exterior : Stairway, Handrails

Stairs Next To Employee Entrance Run 1

#### Finding

There are no handrails provided on the stairway.

**On-Site Finding** None Found

#### Recommendation

Provide compliant handrails.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Add compliant hand	Irail	\$1,528
Code Reference	ADA 504, 505.2, 11B-504.6,CA 11	,

Record Number 168082

Path Of Travel , Walking Surfaces : Walking Surface Slope



Stairway, Handrails : No Handrails



## Stairs - Exterior : Stairway, Risers Striping

**Stairs Next To Employee Entrance** 

Run 1

Stairway, Risers Striping : Risers Striping

## Finding

There is detectable striping affixed to each tread of the stairway, however the strips do not contrast in color from that of the treads or are not at least two inches in width.

**On-Site Finding** None Found

## Recommendation

Replace the detectable striping on each tread of the stairway with detectable striping that clearly contrasts in color and is at least 2 inches in width placed no more than 1 inch from the tread nose or landing.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Add color slip resistant strip to stair \$460 treads

Code Reference ADA 504,CA 11B-504.4.1



## Stairs - Exterior : Stairway

**Stairs Next To Employee Entrance** 

## Finding

Stairway is marked as primary access. There is no other means of vertical access.

**On-Site Finding** No Access

## Recommendation

Provide a compliant means of vertical access.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Modify stairway

\$4,816

Code Reference ADA 210, 504, 206.2, 402.2,CA 11B-206.2,CA 11B-210,CA 11B-402.2,CA 11B-504

Record Number 168081



Stairway

## **Doors - Interior : Door , Latch Side Clearance**

**Computer Literacy Center** Pull Side

## Finding

There is less than the required latch side clearance on the pull side of the door.

**On-Site Finding** 2.00 inches

#### Recommendation

Provide required latch side clearance on the pull side of the door.

Recommendation At least 18.00 inches

## **Costing Info (Estimated)**

Install automatic door opener \$4,000

Code Reference ADA 404, 404.2.4, CA 11B-404.2.4.1

Notes : Shelf obstructs latch side clearance.

Record Number 168075

## Doors - Interior : Door, Hardware

Computer Literacy Center Single Knob

## Finding

The door opening hardware is not accessible.

**On-Site Finding** Not Accessible

#### Recommendation

Provide accessible hardware on the door.

Recommendation See Recommendation

## Costing Info (Estimated)

Replace existing lock set with lever \$800 handled lock set

Code Reference ADA 404.2.7, 309.4, CA 11B-404.2.7

Record Number 168074

Door , Latch Side Clearance : Front Approach Latch Side Clearance



Door , Hardware : Non-Accessible Hardware



## Doors - Interior : Door, Clear Floor Space

**Employee Entrance** Pull Side

## Finding

An unstable floor mat is provided at the door landing.

**On-Site Finding** Not Compliant

#### Recommendation

Provide a compliant floor mat for the door.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Install mat that grips to the floor \$126 surface

Code Reference ADA 403.2, 302.1,CA 11B-302.1,CA 11B-403.2

Record Number 168077

## Doors - Interior : Door, Hardware

Employee Entrance Push Bar / D Handle

## Finding

The door opening force for this door is greater than allowed.

**On-Site Finding** 12.00 pounds

#### Recommendation

Adjust the closer on the door to meet the door opening force requirements.

Recommendation Up to 5.00 pounds

## **Costing Info (Estimated)**


Adjust door closer pressure \$25

Code Reference ADA 404.2.9,CA 11B-404.2.9

Record Number 168076

Door, Clear Floor Space : Floor Mat

Door, Hardware : Door Opening Pressure



## **Doors - Interior : Door , Latch Side Clearance**

Librarian Workroom Push Side

## Finding

There is less than the required latch side clearance on the push side of the door.

**On-Site Finding** 2.00 inches

#### Recommendation

Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.

Recommendation At least 12.00 inches

## **Costing Info (Estimated)**

Install automatic door opener \$2,921

Code Reference ADA 404, 404.2.4, 404.2.4.1,CA 11B-404.2.4.1

Record Number 168121

## Doors - Interior : Door , Latch Side Clearance

Library Director Pull Side

## Finding

There is less than the required latch side clearance on the pull side of the door.

**On-Site Finding** 9.50 inches

#### Recommendation

Provide required latch side clearance on the pull side of the door.

Recommendation At least 18.00 inches

#### Costing Info (Estimated)

Install automatic door opener \$4,000

Code Reference ADA 404, 404.2.4, CA 11B-404.2.4.1

Notes : Furniture obstructs latch side clearance.

Record Number 168039

Door , Latch Side Clearance : Front Approach Latch Side Clearance



Door , Latch Side Clearance : Front Approach Latch Side Clearance

## Doors - Interior : Door, Hardware

Library Director Single Knob

## Finding

The door opening hardware is not accessible.

**On-Site Finding** Not Accessible

## Recommendation

Provide accessible hardware on the door.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Replace existing lock set with lever \$800 handled lock set

Code Reference ADA 404.2.7, 309.4, CA 11B-404.2.7

Record Number 168038

## **Doors - Interior : Door**

**Library Director** 

## Finding

The vertical clearance height of the door is less than required.

**On-Site Finding** 79.50 inches

#### Recommendation

Extend the height of the doorway to provide the required clearance height.

Recommendation At least 80.00 inches

## Costing Info (Estimated)

Install compliant	door
-------------------	------

**Code Reference** ADA 307, 404, 307.4,CA 11B-307,CA 11B-404

\$2,000

Record Number 168037

Door, Hardware: Non-Accessible Hardware



Door : Door Opening Height



## **Doors - Interior : Door , Latch Side Clearance**

Local History Room Pull Side

## Finding

There is less than the required latch side clearance on the pull side of the door.

**On-Site Finding** 2.12 inches

#### Recommendation

Provide required latch side clearance on the pull side of the door.

Recommendation At least 18.00 inches

## **Costing Info (Estimated)**

Install automatic door opener \$4,000

Code Reference ADA 404, 404.2.4, CA 11B-404.2.4.1

The vertical clearance height of the door is less than

Notes : Shelf obstructs latch side clearance.

Record Number 168065

## **Doors - Interior : Door**

Local History Room

Finding

required.

# 

Door, Latch Side Clearance : Front Approach

Latch Side Clearance

Door : Door Opening Height



Costing Info (Estimated)

**On-Site Finding** 79.62 inches

Install compliant door

Recommendation

clearance height. Recommendation

\$2,000

**Code Reference** ADA 307, 404, 307.4,CA 11B-307,CA 11B-404

Extend the height of the doorway to provide the required

At least 80.00 inches

Record Number 168064

Disability Access Consultants (DAC) 1-800-743-7067

## Doors - Interior : Door, Clear Floor Space

## **Main Entrance**

## Finding

There is no level landing at this Automatic door.

**On-Site Finding** 3.70 percent

#### Recommendation

Provide a level landing for the automatic door.

Recommendation Up to 2.08 percent

#### **Costing Info (Estimated)**

Correct slopes

\$1,040 Code Reference ADA 404, 404.2.4.4,CA 11B-404.2.4.4

**Record Number** 217522

## Doors - Interior : Door, Hardware

Staff Unisex Restroom Lever

#### Finding

The door opening force for this door is greater than allowed.

**On-Site Finding** 8.00 pounds

#### Recommendation

Adjust the closer on the door to meet the door opening force requirements.

Recommendation Up to 5.00 pounds

#### **Costing Info (Estimated)**

Adjust door closer pressure \$25

Code Reference ADA 404.2.9,CA 11B-404.2.9





Door, Hardware : Door Opening Pressure



## **Doors - Interior : Door**

Staff Unisex Restroom

## Finding

Has a door stop.

**On-Site Finding** Found

Recommendation

Remove the door stop.

Recommendation See Recommendation

## Costing Info (Estimated)

 Remove door stop
 \$50

 Code Reference
 ADA 404, 404.2.10,CA 11B-404.2.10

Record Number 168116

## Doors - Interior : Door, Latch Side Clearance

Staff Unisex Restroom Pull Side

#### Finding

There is less than the required latch side clearance on the pull side of the door.

**On-Site Finding** 6.12 inches

#### Recommendation

Provide required latch side clearance on the pull side of the door.

Recommendation At least 18.00 inches

#### Costing Info (Estimated)

Install automatic door opener \$4,000

Code Reference ADA 404, 404.2.4, CA 11B-404.2.4.1

Record Number 168117

Door , Latch Side Clearance : Front Approach Latch Side Clearance





Door : Door Hardware



## Doors - Interior : Door, Clear Floor Space

Staff Unisex Restroom Pull Side

## Finding

There is not enough clear floor space provided at the pull side of the door.

On-Site Finding 42.75 inches

#### Recommendation

Provide the recommended clear floor space on the pull side of the door.

Recommendation At least 60.00 inches

## **Costing Info (Estimated)**

Install automatic door opener \$2,921

Code Reference ADA 404, 404.2.4, CA 11B-404.2.4

Record Number 168119

## Doors - Interior : Door, Clear Floor Space

Staff Unisex Restroom Push Side

## Finding

There is not enough clear floor space provided at the push side of the door .

**On-Site Finding** 18.00 inches

#### Recommendation

Provide the recommended clear floor space on the push side of the door.

Recommendation At least 48.00 inches

## **Costing Info (Estimated)**

Install automatic door opener \$4,000

Code Reference ADA 404, 404.2.4, CA 11B-404.2.4.1


Notes : Toilet obstructs clear floor space length.

Record Number 168118

 $\mathsf{Door}$  ,  $\mathsf{Clear}$  Floor Space : Front Approach  $\mathsf{Clear}$  Floor Space Length



Door , Clear Floor Space : Front Approach Clear Floor Space Length



## **Doors - Interior : Door**

## Staff Unisex Restroom

## Finding

The door closing device limits the required headroom clearance.

**On-Site Finding** 77.75 inches

#### Recommendation

Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.

Recommendation At least 78.00 inches

## **Costing Info (Estimated)**

Install new door opener \$250

Code Reference ADA 404, 404.2.3, CA 11B-404.2.3

Record Number 168112

## **Doors - Interior : Door**

**Staff Unisex Restroom** 



Door : Door Closer Vertical Clearance

Door : Door Opening Width

## Finding

The clear opening width of the door is less than required.

On-Site Finding 27.37 inches

## Recommendation

Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.

Recommendation At least 32.00 inches

## Costing Info (Estimated)

Widen existing door and add\$1,750accessible hardware\$1,750

Code Reference ADA 404, 404.2.3, CA 11B-404.2.3



## **Doors - Interior : Door**

## Staff Unisex Restroom

#### Door : Door Opening Height

## Finding

The vertical clearance height of the door is less than required.

**On-Site Finding** 79.37 inches

#### Recommendation

Extend the height of the doorway to provide the required clearance height.

Recommendation At least 80.00 inches

## **Costing Info (Estimated)**

Install compliant door

\$2,000

**Code Reference** ADA 307, 404, 307.4,CA 11B-307,CA 11B-404

Record Number 168114

## Counters - Interior : Library , Checkout Counter

## Adult Library

Checkout

## Finding

The length of the counter or desk does not comply with length requirements. No equivalent facilitation is provided in the area.

On-Site Finding 35.62 inches

#### Recommendation

Provide a counter or desk with the required length.

Recommendation At least 36.00 inches

## **Costing Info (Estimated)**

Provide compliant counter		\$545
Code Reference	ADA 904, 904.4.1	

Record Number 168043



Library , Checkout Counter  $\ : \ {\rm Check} \ {\rm Out} \ {\rm Counter}$  Length



## Signage - Interior : Signage

## **Computer Literacy Center, Local History Room**

## Finding

There is no room identification signage.

**On-Site Finding** None Found

#### Recommendation

Install room identification signage.

Recommendation See Recommendation

**Costing Info (Estimated)** 

Install signage

Code Reference ADA 703, 216, 216.2, CA 11B-216.2

Record Number 168096

## Signage - Exterior : Signage , Signage

## **Directional Signage From The Public Right Of Way**

\$316

\$158

# Signage , Signage : No Directional or Information Signage

## Finding

There is no directional signage.

**On-Site Finding** None Found

## Recommendation

Install directional signage to each accessible element or room.

Recommendation See Recommendation

## **Costing Info (Estimated)**

Install signage

**Code Reference** 

ADA 703, 216, 216.3,CA 11B-216.3, 703.5,CA 11B-703.5

Record Number 168066





Signage : No Room Identification

## Signage - Interior : Signage

**Employee Entrance** 

## Finding

There is no room identification signage.

**On-Site Finding** None Found

## Recommendation

Install room identification signage.


Recommendation See Recommendation

Costing Info (Estimated)Install signage\$158Code ReferenceADA 703, 216, 216.2, CA 11B-216.2

Record Number 168148

## Signage - Interior : Signage

Librarian Workroom





## Finding

There is no room identification signage.

**On-Site Finding** None Found

## Recommendation

Install room identification signage.

Recommendation See Recommendation

**Costing Info (Estimated)** 

Install signage \$158 Code Reference ADA 703, 216, 216.2,CA 11B-216.2



## Signage - Interior : Signage

## **Library Director**

## Finding

There is no room identification signage.

**On-Site Finding** None Found

## Recommendation

Install room identification signage.

Recommendation See Recommendation

Costing Info (Estimated)

Install signage \$158 Code Reference ADA 703, 216, 216.2,CA 11B-216.2

Record Number 168128

## Signage - Interior : Signage , Signage

**Main Entrance** 

## Finding

There is no room signage.

**On-Site Finding** None Found

#### Recommendation

Install accessible room signage.

Recommendation See Recommendation

## Costing Info (Estimated)

Install signage

\$158

**Code Reference** ADA 216.2, 216.6,CA 11B-216.2,CA 11B-216.6

Record Number 168040



Signage , Signage : No Accessible Element/Entrance Signage



### **Restrooms - Interior : Restroom , Toilet**

### **Mens Restroom**

#### Restroom , Toilet : Toilet Distance From Wall

### Finding

The distance from the center of the toilet to the nearest side wall does not meet the required distance.

On-Site Finding 18.37 inches on center

### Recommendation

Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.

Recommendation 17.00 - 18.00 inches

### **Costing Info (Estimated)**

Relocate fixture

\$2,500 Code Reference ADA 603, 604.7, 604.2,CA 11B-604.2

**Record Number** 168105

### **Restrooms - Interior : Restroom , Toilet**

**Mens Restroom** 

### Finding

The height of the toilet seat is not at the required height.

On-Site Finding 16.00 inches

### Recommendation

Adjust or modify the toilet so the seat height is at the required accessible height.

17.00 - 19.00 inches Recommendation

### **Costing Info (Estimated)**

Modify fixture	\$1,707
Code Reference	ADA 603, 604.4,CA 11B-604.4

**Record Number** 168106





Restroom, Toilet: Toilet Seat Height

### **Restrooms - Interior : Restroom , Toilet**

### Mens Restroom

### Finding

The flush control on the toilet is not on the wide (approach) side of the toilet.

On-Site Finding Wrong Side of Toilet

#### Recommendation

Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Relocate flush valve \$127

Code Reference ADA 603, 604.6,CA 11B-604.6

Record Number 168108

### **Restrooms - Interior : Restroom , Grab Bars**

Mens Restroom

### Finding

The distance from the rear wall to the side grab bar is greater than allowed.

**On-Site Finding** 12.50 inches

### Recommendation

Remount the side grab bar so it meets the distance requirements from the back wall.

Recommendation Up to 12.00 inches

### **Costing Info (Estimated)**

Provide compliant grab	bar	\$267
------------------------	-----	-------

Code Reference ADA 603, 609, 604.5.1,CA 11B-604.5.1

Record Number 168109

Restroom , Grab Bars : Grab Bar Distance From Back Wall







### Restrooms - Interior : Restroom , Grab Bar

Mens Restroom

### Finding

Rear grab bar location is not compliant.

**On-Site Finding** Not Compliant

### Recommendation

Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the side.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Provide a compliant back grab bar. \$267

Code Reference ADA 604.5.2,CA 11B-604.5.2

Record Number 168110

### **Restrooms - Interior : Restroom , Toilet Compartment**

Mens Restroom

### Finding

The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.

On-Site Finding 10.00 inches

#### Recommendation

Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow continuous paper flow and shall not interfere with the use of the side grab bar.

Recommendation 7.00 - 9.00 inches

### **Costing Info (Estimated)**

Provide compliant dispenser \$277

Code Reference ADA 603, 604.7,CA 11B-604.7,CA 11B-309.4

Record Number 168111

Restroom , Toilet Compartment : Toilet Paper Dispenser Distance From Seat



CEPES

Restroom, Grab Bar: Rear Grab Bar Location

### Restrooms - Interior : Restroom, Mirror

### **Mens Restroom**

### Finding

The bottom edge of the reflective surface of the mirror is not at the correct height.

On-Site Finding 41.00 inches

#### Recommendation

Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.

Recommendation Up to 40.00 inches

### **Costing Info (Estimated)**

Lower mirror

**Code Reference** ADA 603, 213, 603.3, CA 11B-603.3

**Record Number** 168135

### Restrooms - Interior : Restroom , Door Signage

\$300

**Mens Restroom Door Sign - Male** 

### Finding

The gender use signage on the entrance door is not mounted at the required height.

**On-Site Finding** 60.50 inches

#### Recommendation

Post gender use signage on the center of the door at the required height.

58.00 - 60.00 inches Recommendation

### **Costing Info (Estimated)**

Install signage	\$158
Code Reference	CA 11B-703.7.2.6

**Record Number** 168136

Restroom, Door Signage : Door Signage Height





Restroom , Mirror : Mirror Bottom Edge Height

Disability Access Consultants (DAC) 1-800-743-7067

### Restrooms - Interior : Restroom , Lavatory

Mens Restroom Lavatory

#### Restroom , Lavatory : Lavatory Surface Height

### Finding

The height of the counter surface is greater than allowed.

**On-Site Finding** 34.12 inches

### Recommendation

Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.

Recommendation Up to 34.00 inches

### **Costing Info (Estimated)**

Provide compliant lavatory \$1,286

Code Reference ADA 213, 606, 606.3,CA 11B-213,CA 11B-606.3

Record Number 168133

### **Restrooms - Interior : Restroom , Lavatory**

Mens Restroom Lavatory

### Finding

Supply lines are not wrapped at the lavatory.

**On-Site Finding** Not Wrapped

#### Recommendation

Wrap the supply lines around lavatory according to compliance.

Recommendation See Recommendation

### Costing Info (Estimated)

Wrap supply lines	\$149
Code Reference	ADA 213, 606, 606.5,CA 11B-606.5

Record Number 168134



Restroom , Lavatory : Lavatory - Supply Lines not wrapped



### **Restrooms - Interior : Restroom , Dispensers**

**Mens Restroom** Soap

### Finding

The height of the controls and operating mechanisms for the dispenser is not at the correct height.

**On-Site Finding** 42.50 inches

### Recommendation

Relocate the dispenser to the correct height.

Recommendation Up to 40.00 inches

### **Costing Info (Estimated)**

Provide compliant dispenser \$277

Code Reference ADA 309, 205, 308, 606, 308.1,CA 11B-603.5

**Record Number** 168132

### Restrooms - Interior : Restroom, Wall Signage

**Mens Restroom** Wall Sign

### Finding

There is no signage indicating accessibility on the latch side of the entry door of the restroom.

**On-Site Finding** None Found

#### Recommendation

Provide compliant signage on latch side of door.

Recommendation See Recommendation

# **Costing Info (Estimated)**

Install signage \$158 Code Reference ADA 703, 216, 216.8, CA 11B-216.8 168137

Record Number



Restroom, Dispensers : Dispenser Height

Restroom , Wall Signage : No Wall Signage



Disability Access Consultants (DAC) 1-800-743-7067

### **Restrooms - Interior : Restroom**

Mens Restroom

Restroom : Circular Turning Space Diameter

### Finding

There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.

**On-Site Finding** 56.00 inches

### Recommendation

Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.

Recommendation At least 60.00 inches

### **Costing Info (Estimated)**

Install single-use toilet room \$14,000

Code Reference ADA 603, 304, 304.3.1, 603.2.1, 304.3, 603.2,CA 11B-304.3

Notes : Circular turning space reduced by lavatory.

Record Number 168131

### **Restrooms - Interior : Restroom , Toilet**

Staff Unisex Restroom

### Finding

The distance from the center of the toilet to the nearest side wall does not meet the required distance.

On-Site Finding 21.25 inches on center

### Recommendation


Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.

Recommendation 17.00 - 18.00 inches

### Costing Info (Estimated)

Relocate fixture	\$2,500
Code Reference	ADA 603, 604.7, 604.2,CA 11B-604.2
	1 600 50

Record Number 168050



Restroom , Toilet : Toilet Distance From Wall



# **Restrooms - Interior : Restroom , Toilet**

Staff Unisex Restroom

### Finding

The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.

### **On-Site Finding** 21.50 inches

### Recommendation

Locate the toilet in a space which provides the required clearances.

Recommendation At least 42.00 inches

### **Costing Info (Estimated)**

Relocate fixture \$2,500

Code Reference ADA 603, 604.2,CA 11B-604.2

Record Number 168052

### **Restrooms - Interior : Restroom , Toilet**

**Staff Unisex Restroom** 

### Finding

There is less than the required minimum space in front of the toilet.

**On-Site Finding** 40.12 inches

### Recommendation

Create the required minimum clear space in front of the toilet.

Recommendation At least 48.00 inches

### **Costing Info (Estimated)**

Modify space	\$3,500
Code Reference	ADA 603,CA 11B-604.8.1
	4 600 50

Record Number 168053





Restroom , Toilet : Toilet Clear Floor Space



### Restrooms - Interior : Restroom , Grab Bars

Staff Unisex Restroom

### Finding

The length of the side grab bar is less than required.

**On-Site Finding** 18.00 inches

### Recommendation

Replace the side grab bar with a compliant grab bar.

Recommendation At least 42.00 inches

### **Costing Info (Estimated)**

Provide compliant grab bar \$267

Code Reference ADA 603, 609, 604.5.1,CA 11B-604.5.1

Record Number 168054

### **Restrooms - Interior : Restroom , Grab Bars**

**Staff Unisex Restroom** 

### Finding

The distance from the rear wall to the side grab bar is greater than allowed.

**On-Site Finding** 14.75 inches

### Recommendation

Remount the side grab bar so it meets the distance requirements from the back wall.

Recommendation Up to 12.00 inches

### Costing Info (Estimated)


Provide compliant g	rab bar	\$267
Code Reference	ADA 603, 609, 11B-604.5.1	604.5.1,CA

Record Number 168055



Restroom , Grab Bars : Side Grab Bar Length

Restroom , Grab Bars : Grab Bar Distance From Back Wall



### Restrooms - Interior : Restroom , Grab Bars

Staff Unisex Restroom

### Finding

The distance from the back wall to the front of the grab bar is less than required.

**On-Site Finding** 32.75 inches

#### Recommendation

Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.

Recommendation At least 54.00 inches

### **Costing Info (Estimated)**

Provide compliant grab bar \$267

Code Reference ADA 603, 609, 604.5.1,CA 11B-604.5.1,CA 11B-609

Record Number 168056

### Restrooms - Interior : Restroom , Grab Bars

Staff Unisex Restroom

### Finding

The distance from the front edge of the toilet to the front edge of the side grab bar is insufficient.

**On-Site Finding** 2.75 inches

#### Recommendation

Install or relocate the side grab bar so that the distance from the front edge of the toilet to the front edge of the side grab bar meets the required minimum distance.

Recommendation At least 24.00 inches

### **Costing Info (Estimated)**

Provide compliant g	jrab bar	\$267
---------------------	----------	-------

Code Reference CA 11B-604.5.1

Record Number 168057





Restroom , Grab Bars : Distance from Front Edge of Toilet to Front of Grab Bar



### **Restrooms - Interior : Restroom , Grab Bars**

**Staff Unisex Restroom** 

### Finding

The height of the side grab bar is not at the correct height.

**On-Site Finding** 31.25 inches

#### Recommendation

Remount the grab bar so it is at the correct height.

33.00 - 36.00 inches Recommendation

### **Costing Info (Estimated)**

Relocate compliant grab bars and \$500 patch

**Code Reference** ADA 603, 609, 609.4, CA 11B-609.4,CA 11B-604.5

**Record Number** 168058

### **Restrooms - Interior : Restroom , Toilet Compartment**

Staff Unisex Restroom

### Finding

The coat hook is not mounted at the correct height.

On-Site Finding 63.37 inches

### Recommendation

Mount the coat hook at the recommended height.

Recommendation 15.00 - 48.00 inches

### **Costing Info (Estimated)**

Move coat hook	\$50
Code Reference	ADA 308, 603.4, 308.1,CA 11B-308,CA 11B-603.4,CA 11B-604.8.3

Record Number 168059 Restroom, Toilet Compartment : Coat Hook Height



Restroom , Grab Bars : Side Grab Bar Height



### **Restrooms - Interior : Restroom , Toilet Compartment**

Staff Unisex Restroom

### Finding

The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.

**On-Site Finding** 1.00 inches

### Recommendation

Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow continuous paper flow and shall not interfere with the use of the side grab bar.

Recommendation 7.00 - 9.00 inches

### **Costing Info (Estimated)**

Provide compliant dispenser \$277

**Code Reference** ADA 603, 604.7,CA 11B-604.7,CA 11B-309.4

Record Number 168060

### Restrooms - Interior : Restroom, Door Signage

Staff Unisex Restroom

Door Sign - Unisex

### Finding

There is no gender use signage on the entrance door.

**On-Site Finding** None Found

### Recommendation

Post gender use signage on the center of the door at the required height.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Install signage	\$158
Code Reference	CA 11B-216.8,CA 11B-703.7.2.6
Record Number	168178

Restroom , Toilet Compartment : Toilet Paper Dispenser Distance From Seat



Restroom , Door Signage : No Door Signage



### **Restrooms - Interior : Restroom , Lavatory**

Staff Unisex Restroom Lavatory

Restroom , Lavatory : Lavatory Type

### Finding

The lavatory is in an enclosed cabinet, thereby preventing an accessible forward approach.

On-Site Finding Not Accessible

#### Recommendation

Lavatories in restrooms must provide clear floor space in front of the lavatory for an accessible forward approach and shall provide the minimum required primary age group knee and toe clearances. If sufficient clear floor space and compliant clearances can not be provided, remove the lavatory cabinet and replace with an accessible wall-mounted lavatory unit.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Remove base cabinets, add\$420additional bracingADA 213, 606, 606.2,CA

11B-606.2,CA 11B-305,CA 11B-306

Record Number 168170



### **Restrooms - Interior : Restroom , Lavatory**

Staff Unisex Restroom Lavatory

### Finding

The apron height under the lavatory is less than the required minimum height.

**On-Site Finding** 24.00 inches

### Recommendation

Raise or replace the lavatory to provide the minimum required apron height.

Recommendation At least 29.00 inches

### **Costing Info (Estimated)**

Provide compliant lavatory	\$2,500
----------------------------	---------

Code Reference ADA 213, 606, 306.3,CA 11B-306.3.3,CA 11B-606.2

Record Number 168171

Restroom , Lavatory : Lavatory Apron Height



### **Restrooms - Interior : Restroom , Lavatory**

Staff Unisex Restroom Lavatory

### Finding

The knee clearance space under the lavatory is less than the required minimum height.

**On-Site Finding** 24.00 inches

#### Recommendation

Raise or replace the lavatory to provide the minimum required knee clearance.

Recommendation At least 27.00 inches

### **Costing Info (Estimated)**

Provide compliant lavatory \$1,286

Code Reference ADA 213, 606, 606.2, 306.3.1,CA 11B-606.2,CA 11B-306.3.1

Record Number 168172

### **Restrooms - Interior : Restroom , Lavatory**

Staff Unisex Restroom Lavatory

### Finding

There is not sufficient clear floor space provided to allow an accessible forward approach.

**On-Site Finding** 9.87 inches

#### Recommendation

Relocate the lavatory to provide clear floor space.

Recommendation At least 30.00 inches

### Costing Info (Estimated)

Install new sink, faucet and handles \$2,261

Code Reference ADA 213, 606, 606.2, 305.3,CA 11B-606.2,CA 11B-305

Record Number 168173

 ${\sf Restroom}$  ,  ${\sf Lavatory}$  :  ${\sf Lavatory}$   ${\sf Clear}$   ${\sf Floor}$   ${\sf Space}$   ${\sf Width}$ 



Restroom , Lavatory : Lavatory Knee Clearance

Disability Access Consultants (DAC) 1-800-743-7067



### Restrooms - Interior : Restroom , Lavatory

Staff Unisex Restroom Lavatory

### Finding

There is not sufficient clear floor space provided to allow an accessible forward approach.

**On-Site Finding** 19.37 inches

#### Recommendation

Relocate the lavatory to provide clear floor space.

Recommendation At least 48.00 inches

### **Costing Info (Estimated)**

Install new sink, faucet and handles \$2,261

Code Reference ADA 213, 606, 606.2, 305.3,CA 11B-606.2,CA 11B-305

Record Number 168174

### **Restrooms - Interior : Restroom , Lavatory**

Staff Unisex Restroom Lavatory

### Finding

The pipes under the lavatory do not provide protection against contact.

**On-Site Finding** Pipes not wrapped.

### Recommendation

Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.

Recommendation See Recommendation

### Costing Info (Estimated)

 Wrap pipes
 \$149

 Code Reference
 ADA 213, 606, 606.5, CA 11B-606.5

 Record Number
 168175

Restroom , Lavatory : Lavatory Clear Floor Space Length



Restroom , Lavatory : Lavatory Pipes Not Wrapped



### Restrooms - Interior : Restroom , Lavatory

Staff Unisex Restroom Lavatory

### Finding

Supply lines are not wrapped at the lavatory.

**On-Site Finding** Not Wrapped

### Recommendation

Wrap the supply lines around lavatory according to compliance.

Recommendation See Recommendation

### Costing Info (Estimated)

 Wrap supply lines
 \$149

 Code Reference
 ADA 213, 606, 606.5, CA 11B-606.5

**Record Number** 168176

### **Restrooms - Interior : Restroom , Dispensers**

Staff Unisex Restroom Paper Towel

### Finding

The height of the controls and operating mechanisms for the dispenser is not at the correct height.

**On-Site Finding** 50.50 inches

### Recommendation

Relocate the dispenser to the correct height.

Recommendation Up to 40.00 inches

### **Costing Info (Estimated)**

Provide compliant dispenser \$277

**Code Reference** ADA 309, 205, 308, 606, 308.1,CA 11B-603.5

Record Number 168169





Restroom, Dispensers : Dispenser Height



### **Restrooms - Interior : Restroom , Mirror**

Staff Unisex Restroom

### Finding

The bottom edge of the reflective surface of the mirror is not at the correct height.

**On-Site Finding** 47.25 inches

### Recommendation

Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.

Recommendation Up to 40.00 inches

### **Costing Info (Estimated)**

Lower mirror

Code Reference ADA 603, 213, 603.3, CA 11B-603.3

Record Number 168177

### **Restrooms - Interior : Restroom , Wall Signage**

\$300

Staff Unisex Restroom Wall Sign

### Finding

There is no signage indicating accessibility on the latch side of the entry door of the restroom.

**On-Site Finding** None Found

### Recommendation

Provide compliant signage on latch side of door.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Install signage	\$158
Code Reference	ADA 703, 216, 216.8,CA 11B-216.8
Record Number	168179





Restroom , Wall Signage : No Wall Signage

Restroom , Mirror : Mirror Bottom Edge Height

### **Restrooms - Interior : Restroom , Toilet Compartment**

Staff Unisex Restroom

### Finding

The location of the seat cover dispenser does not provide sufficient clear floor space.

**On-Site Finding** Not Accessible

### Recommendation

Relocate the seat cover dispenser so it provides sufficient clear floor space and does not interfere with the use of a grab bar. Make certain that the height of all operable parts of the seat cover dispenser is within reach range above the finished floor.

Recommendation See Recommendation


### **Costing Info (Estimated)**

Provide compliant dispenser \$277

Code Reference ADA 304, 309.2, 305.1,CA 11B-603.5,CA 11B-309.2,CA 11B-305.1

Record Number 168046

Restroom , Toilet Compartment : Seat Cover Dispenser Behind Toilet



### **Restrooms - Interior : Restroom , Toilet Compartment**

**Staff Unisex Restroom** 

### Finding

There is not a minimum of 60 inches of clearance around the water closet measured perpendicular from the side wall.

**On-Site Finding** 43.00 inches

### Recommendation

Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured perpendicular from the rear wall.

Recommendation At least 60.00 inches

### **Costing Info (Estimated)**

Modify fixture	\$1,707
Code Reference	ADA 603, 502.4, 604.3.1
Record Number	168047

 $\ensuremath{\mathsf{Restroom}}$  , Toilet Compartment  $\ : \ \ensuremath{\mathsf{Toilet}}$  Clear Floor Space Width



### Restrooms - Interior : Restroom , Grab Bars

Staff Unisex Restroom

### Finding

There is no back grab bar at the toilet compartment.

**On-Site Finding** None Found

### Recommendation

Install the required grab bars in the toilet compartment.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Provide compliant grab bar \$267

Code Reference ADA 603, 604.5, 604.8.1.5,CA 11B-604.5,CA 11B-604.8.1.5

Record Number 168048



Restroom , Grab Bars : No Back Wall Grab Bar

### **Restrooms - Interior : Restroom , Toilet Compartment**

**Staff Unisex Restroom** 

Restroom , Toilet Compartment : Seat Cover Dispenser Height

### Finding

The height of the operable parts of the seat cover dispenser is greater than the allowed maximum height.

**On-Site Finding** 47.00 inches

### Recommendation

Lower the seat cover dispenser so the height of all operable parts meets the required accessible height. Make certain that the location of the seat cover dispenser does not interfere with the use of a grab bar.

Recommendation Up to 40.00 inches

### Costing Info (Estimated)

Provide compliant dispenser \$277

**Code Reference** ADA 309, 205, 308, 606, 308.2,CA 11B-603.5

Record Number 168049



### **Restrooms - Interior : Restroom**

**Staff Unisex Restroom** 

### Finding

The restroom door does not provide a compliant privacy lock with occupancy indicator.

**On-Site Finding** None Found

#### Recommendation

Install a compliant privacy lock with occupancy indicator to the door.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Replace existing lock set with lever \$804 handled lock set

Code Reference ADA 213, 213.2.1, CA 11B-213.2.1

Record Number 168167

### **Restrooms - Interior : Restroom**

**Staff Unisex Restroom** 

Restroom : No Door Privacy Lock and Occupied Indicator



Restroom : Circular Turning Space Diameter

### Finding

There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.

**On-Site Finding** 19.37 inches

### Recommendation

Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.

Recommendation At least 60.00 inches

### **Costing Info (Estimated)**

Install single-use toilet room \$14,000

 
 Code Reference
 ADA 603, 304, 304.3.1, 603.2.1, 304.3, 603.2,CA 11B-304.3

Record Number 168168



### **Restrooms - Interior : Restroom , Toilet**

Womens Restroom

#### Restroom , Toilet : Toilet Distance From Wall

### Finding

The distance from the center of the toilet to the nearest side wall does not meet the required distance.

**On-Site Finding** 18.37 inches on center

### Recommendation

Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.

Recommendation 17.00 - 18.00 inches

### Costing Info (Estimated)

 Relocate fixture
 \$2,500

 Code Reference
 ADA 603, 604.7, 604.2,CA

 11B-604.2

Record Number 168122

### **Restrooms - Interior : Restroom , Toilet**

Womens Restroom

### Finding

The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.

**On-Site Finding** 41.75 inches

### Recommendation

Locate the toilet in a space which provides the required clearances.

Recommendation At least 42.00 inches

### Costing Info (Estimated)

Relocate fixture	\$2,500
Code Reference	ADA 603, 604.2,CA 11B-604.2

Record Number 168124



Restroom , Toilet : Toilet Minimum Distance From Any fixture



### **Restrooms - Interior : Restroom , Grab Bars**

Womens Restroom

### Finding

The distance from the back wall to the front of the grab bar is less than required.

**On-Site Finding** 52.25 inches

#### Recommendation

Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.

Recommendation At least 54.00 inches

### **Costing Info (Estimated)**

Provide compliant grab bar \$267

Code Reference ADA 603, 609, 604.5.1,CA 11B-604.5.1,CA 11B-609

Record Number 168125

### Restrooms - Interior : Restroom , Grab Bars

Womens Restroom

### Finding

The distance from the front edge of the toilet to the front edge of the side grab bar is insufficient.

On-Site Finding 23.75 inches

### Recommendation

Install or relocate the side grab bar so that the distance from the front edge of the toilet to the front edge of the side grab bar meets the required minimum distance.

Recommendation At least 24.00 inches

### **Costing Info (Estimated)**

Provide compliant	grab bar	\$267
-------------------	----------	-------

Code Reference CA 11B-604.5.1

Record Number 168126





Restroom , Grab Bars : Distance from Front Edge of Toilet to Front of Grab Bar



### Restrooms - Interior : Restroom, Grab Bar

**Womens Restroom** 

### Finding

Rear grab bar location is not compliant.

On-Site Finding Not Compliant

### Recommendation

Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the side.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Provide a compliant back grab bar. \$267

**Code Reference** ADA 604.5.2,CA 11B-604.5.2

Record Number 168127

### **Restrooms - Interior : Restroom , Lavatory**

**Womens Restroom** Lavatory

### Finding

The height of the counter surface is greater than allowed.

**On-Site Finding** 34.12 inches

### Recommendation

Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.

Up to 34.00 inches Recommendation

### Costing Info (Estimated)

Provide compliant lavatory


Code Reference ADA 213, 606, 606.3, CA 11B-213, CA 11B-606.3

\$1,286

**Record Number** 168141



Restroom , Grab Bar : Rear Grab Bar Location



### Restrooms - Interior : Restroom , Lavatory

Womens Restroom Lavatory

-

### Finding

The lavatory does not meet the minimum required distance to the center line of the fixture, when located adjacent to a side wall, partition or fixture.

On-Site Finding 17.62 inches on center

### Recommendation

Replace or remount lavatory to meet the minimum required distance to the center line of the fixture, when located adjacent to a side wall or partition.

Recommendation At least 18.00 inches on center

### **Costing Info (Estimated)**

Install new sink, faucet and handles \$2,500

Code Reference CA 11B-606.6

Record Number 168142

### Restrooms - Interior : Restroom , Lavatory

Womens Restroom Lavatory

### Finding

Supply lines are not wrapped at the lavatory.

**On-Site Finding** Not Wrapped

### Recommendation

Wrap the supply lines around lavatory according to compliance.

Recommendation See Recommendation

### Costing Info (Estimated)

 Wrap supply lines
 \$149

 Code Reference
 ADA 213, 606, 606.5, CA 11B-606.5

Record Number 168143

Restroom , Lavatory : Lavatory Distance From Wall/Fixture



Restroom , Lavatory : Lavatory - Supply Lines not wrapped



Disability Access Consultants (DAC) 1-800-743-7067

### **Restrooms - Interior : Restroom , Dispensers**

Womens Restroom Paper Towel

#### Restroom , Dispensers : Dispenser Height

### Finding

The height of the controls and operating mechanisms for the dispenser is not at the correct height.

**On-Site Finding** 40.50 inches

#### Recommendation

Relocate the dispenser to the correct height.

Recommendation Up to 40.00 inches

### **Costing Info (Estimated)**

Provide compliant dispenser \$277

**Code Reference** ADA 309, 205, 308, 606, 308.1,CA 11B-603.5

Record Number 168140

### **Restrooms - Interior : Restroom , Dispensers**

Womens Restroom Soap

### Finding

The height of the controls and operating mechanisms for the dispenser is not at the correct height.

**On-Site Finding** 44.00 inches

### Recommendation

Relocate the dispenser to the correct height.

Recommendation Up to 40.00 inches

### Costing Info (Estimated)

Provide compliant dispenser \$277

**Code Reference** ADA 309, 205, 308, 606, 308.1,CA 11B-603.5

Record Number 168139



Restroom , Dispensers : Dispenser Height



Page 63 of 77

### **Restrooms - Interior : Restroom , Mirror**

Womens Restroom

### Finding

The bottom edge of the reflective surface of the mirror is not at the correct height.

**On-Site Finding** 41.00 inches

#### Recommendation

Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.

Recommendation Up to 40.00 inches

### **Costing Info (Estimated)**

Lower mirror

Code Reference ADA 603, 213, 603.3, CA 11B-603.3

Record Number 168144

### **Restrooms - Interior : Restroom , Wall Signage**

\$300

Womens Restroom Wall Sign

### Finding

There is no signage indicating accessibility on the latch side of the entry door of the restroom.

**On-Site Finding** None Found

### Recommendation

Provide compliant signage on latch side of door.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Install signage	\$158
Code Reference	ADA 703, 216, 216.8,CA 11B-216.8

Record Number 168145



Restroom , Mirror : Mirror Bottom Edge Height

Restroom , Wall Signage : No Wall Signage



### **Restrooms - Interior : Restroom**

Womens Restroom

Restroom : Circular Turning Space Diameter

### Finding

There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.

**On-Site Finding** 58.50 inches

### Recommendation

Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.

Recommendation At least 60.00 inches

### **Costing Info (Estimated)**

Install single-use toilet room \$14,000

**Code Reference** ADA 603, 304, 304.3.1, 603.2.1, 304.3, 603.2,CA 11B-304.3

Notes : Circular turning space reduced by toilet.

Record Number 168138

### **Drinking Fountains - Interior : Drinking Fountain**

**Drinking Fountain Next To Restrooms** 

### Finding

The provided drinking fountain is not a Hi-Low fountain.

**On-Site Finding** Fountain Not Compliant

### Recommendation

Replace the drinking fountain with a compliant Hi-Low fountain.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Install new high/low fountain	\$2,500
-------------------------------	---------

Code Reference ADA 305, 602, 211.2,CA 11B-211.2,CA 11B-602

Record Number 168084





Drinking Fountain : Fountain Type

Page 65 of 77

# Drinking Fountains - Interior : Drinking Fountain

# **Drinking Fountain Next To Restrooms**

# Finding

There is less than the required minimum knee clearance height.

**On-Site Finding** 19.75 inches

# Recommendation

Provide a fountain with the required knee and toe clearances.

Recommendation At least 27.00 inches

# Costing Info (Estimated)

Install new high/low fountain \$2,500

 
 Code Reference
 ADA 305, 306, 211, 602, 306.3, 602.2,CA 11B-602.2,CA 11B-305

Record Number 168085

# Drinking Fountains - Interior : Drinking Fountain

**Drinking Fountain Next To Restrooms** 

Drinking Fountain : Spout Height

# Finding

The spout outlet height is greater than required.

**On-Site Finding** 36.62 inches

# Recommendation

Provide a spout outlet that does not exceed the required height.

Recommendation Up to 36.00 inches

# Costing Info (Estimated)

Install new wall-mounted fountain \$627 Code Reference ADA 211, 602, 602.4,CA 11B-602.4

Record Number 168086





Drinking Fountain : Knee Clearance

### **Drinking Fountains - Interior : Drinking Fountain**

**Drinking Fountain Next To Restrooms** 

### Finding

The height of the water stream is less than required.

**On-Site Finding** 2.00 inches

### Recommendation

Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of the drinking fountain.

Recommendation At least 4.00 inches

### Costing Info (Estimated)

Install new high/low fountain \$2,500

**Code Reference** ADA 211, 602, 602.6,CA 11B-211,CA 11B-602

Record Number 168087

### **Drinking Fountains - Interior : Drinking Fountain**

**Drinking Fountain Next To Restrooms** 

### Finding

Drinking fountain does not provide a required fountain depth.

**On-Site Finding** 13.25 inches

### Recommendation

Install a drinking fountain the meets the required minimum depth.

Recommendation At least 18.00 inches

### Costing Info (Estimated)

Install new wall-mounted fountain \$2,500

Code Reference ADA 305, 306, 211, 602,CA 11B-602.8

Record Number 168088



Drinking Fountain : Stream Height



Drinking Fountain : Fountain Depth

### **Drinking Fountains - Interior : Drinking Fountain**

### **Drinking Fountain Next To Restrooms**

### Finding

The drinking fountain is not set entirely in an alcove.

### **On-Site Finding** None Found

#### Recommendation

If the drinking fountain is not set in an alcove it shall provide a side rail or wing wall next to each side of the fountain to prevent it from protruding into the primary path of travel.

Recommendation See Recommendation

### Costing Info (Estimated)

Install wing walls or relocate object \$640

Code Reference ADA 307.2, 602.1, CA 11B-602.9

Record Number 168089

### Libraries - Interior : Library, Aisles

Adult Library End/Side

### Finding

The width of side and end aisles is less than 36 inches.

On-Site Finding 19.75 inches

### Recommendation

Move the book stacks to provide the required access width between the aisles.

Recommendation At least 36.00 inches

### Costing Info (Estimated)

 Provide compliant shelves
 \$1,080

 Code Reference
 ADA 403, 403.5.1,CA 11B-403.5.1

Record Number 168041



Drinking Fountain : No Detectable Warnings

Library, Aisles : End Aisle Width



### Libraries - Interior : Library , Aisles

Adult Library Main

### Finding

The space between book shelves is less than required value.

**On-Site Finding** 36.50 inches

#### Recommendation

Increase the space between shelves to the recommended value.

Recommendation At least 44.00 inches

### **Costing Info (Estimated)**

Provide compliant shelves \$2,160

Code Reference ADA 403,CA 11B-403.5.1

Record Number 168042

# Libraries - Interior : Library, Table

Adult Library Tables

### Finding

There is not enough clear floor space at the library table.

**On-Site Finding** 26.37 inches

### Recommendation

Provide compliant clear floor space for the library table.

Recommendation At least 30.00 inches

Costing Info (Estimated)

\$1,840 **Code Reference** ADA 306, 902.2, 902.4.1,CA 11B-902.2,CA 11B-306,CA 11B-902.4.1

Record Number 168044



Library , Aisles : Aisle Width between Shelves

Library , Table : Clear Floor Space Width



Disability Access Consultants (DAC) 1-800-743-7067

### Libraries - Interior : Library , Aisles

Childrens Library Main

### Finding

The space between book shelves is less than required value.

**On-Site Finding** 35.62 inches

#### Recommendation

Increase the space between shelves to the recommended value.

Recommendation At least 44.00 inches

### **Costing Info (Estimated)**

Provide compliant shelves \$2,160

Code Reference ADA 403,CA 11B-403.5.1

Record Number 168061

### Libraries - Interior : Library, Table

Childrens Library Tables

### Finding

There is not enough clear floor space at the library table.

**On-Site Finding** 26.75 inches

### Recommendation

Provide compliant clear floor space for the library table.

Recommendation At least 30.00 inches

Costing Info (Estimated)

\$1,840 **Code Reference** ADA 306, 902.2, 902.4.1,CA 11B-902.2,CA 11B-306,CA 11B-902.4.1

Record Number 168062



Library , Table : Clear Floor Space Width



Disability Access Consultants (DAC) 1-800-743-7067



Library , Aisles : Aisle Width between Shelves

### **Emergency Warning Systems - Interior : Emergency Warning Systems**

Visual Alarms

### Finding

There are no visual warning devices at the facility.

**On-Site Finding** None Found

### Recommendation

Install visual warning devices integrated with the facility's alarm system in all common areas such as hallways, classrooms and general use rooms, and in accessible restrooms and other accessible rooms.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Install new audible/visual alarm \$2,200

Code Reference ADA 215, 702,CA 11B-215,CA 11B-702

Record Number 168079

### Break/Conference Room - Interior : Break Room

Librarian Break Room

Paper Towel

### Finding

The height of the controls and operating mechanisms for the dispenser is not at the correct height.

**On-Site Finding** 50.00 inches

### Recommendation

Relocate the dispenser to the correct height.

Recommendation Up to 40.00 inches


### Costing Info (Estimated)

 Relocate dispenser
 \$110

 Code Reference
 ADA 309, 205, 308, 606, CA

 11B-603.5

Record Number 168103





Break Room : Break Room



# Break/Conference Room - Interior : Break Room

Librarian Break Room Sink

### Finding

Sink counter height does not meet the standards.

On-Site Finding 36.00 inches

### Recommendation

Provide compliant sink.

Recommendation Up to 34.00 inches

### **Costing Info (Estimated)**

Provide compliant sink \$1,800

**Code Reference** ADA 309, 205, 308, 904, 228,CA 11B-606.3

Record Number 168097

### Break/Conference Room - Interior : Break Room

Librarian Break Room Sink

### Finding

The toe kick for the sink in break/conference room is not removed.

**On-Site Finding** Not Removed

### Recommendation

Remove the toe kick for the sink.

Recommendation See Recommendation

### **Costing Info (Estimated)**

\$612 **Code Reference** ADA 309, 305, 205, 308, 228, 606.2,CA 11B-606.2,CA 11B-305,CA 11B-306

Record Number 168098



Break Room : Sink - Counter Height

Break Room : Toe Kick Not Removed



# Break/Conference Room - Interior : Break Room

Librarian Break Room Sink

### Finding

The pipes are not wrapped for the sink.

**On-Site Finding** Not Wrapped

### Recommendation

Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.

Recommendation See Recommendation

### **Costing Info (Estimated)**

Wrap pipes \$149

**Code Reference** ADA 309, 205, 308, 228, 606.5,CA 11B-606.5

Record Number 168099

### Break/Conference Room - Interior : Break Room , Sink

Librarian Break Room Sink

### Finding

There is not enough clear floor space at the sink.

**On-Site Finding** 46.00 inches

#### Recommendation

Provide enough clear floor space at the location.

Recommendation At least 48.00 inches

### Costing Info (Estimated)

Unknown scope	\$900
Code Reference	ADA 309, 205, 308, 228
Record Number	168101

Break Room : Pipes not Wrapped





Break Room , Sink : Clear Floor Space Length

Disability Access Consultants (DAC) 1-800-743-7067

### Break/Conference Room - Interior : Break Room , Sink

Librarian Break Room Sink

### Finding

Supply lines are not wrapped for the break/conference room sink.

**On-Site Finding** Not Wrapped

#### Recommendation

Make sure that the supply lines are fully wrapped and insulated for the sink.

Recommendation See Recommendation

### Costing Info (Estimated)

 Wrap pipes
 \$149

 Code Reference
 ADA 606.5,CA 11B-606.5

**Record Number** 168102

### Break/Conference Room - Interior : Break Room

Librarian Break Room Soap

### Finding

The height of the controls and operating mechanisms for the dispenser is not at the correct height.

\$110

**On-Site Finding** 47.00 inches

#### Recommendation

Relocate the dispenser to the correct height.

Recommendation Up to 40.00 inches

### **Costing Info (Estimated)**

Relocate dispenser

**Code Reference** ADA 309, 205, 308, 606,CA 11B-603.5

Record Number 168104



Break Room , Sink : Supply Lines

Break Room : Break Room



### Picnic Areas - Exterior : Picnic Tables

**Picnic Tables Next To Main Entrance** 

### Finding

At least 5% of the provided tables are not accessible.

**On-Site Finding** None Found

#### Recommendation

Provide enough compliant Accessible Tables (At least 5% of the total Tables).

Recommendation At least 1.00 tables

### **Costing Info (Estimated)**

Accessible table (each) \$500 **Code Reference** ADA 309, 305, 205, 306, 308, 902, 228, 226.1

Record Number 168129



# **Reach Ranges - Interior : Reach Range , Element Highest Point of Operation**

**Computer Literacy Center** 

Printer Change Machine - Other

### Finding

The highest point of operation for the element is not compliant.

On-Site Finding 50.00 inches

#### Recommendation

Make sure that the highest point of operation is within the recommended value.

Recommendation 15.00 - 48.00 inches

### Costing Info (Estimated)

Readjust element height \$50

Code Reference ADA 309, 304, 308, 902.4.2,CA 11B-308,CA 11B-902.4.2

Record Number 168045

Reach Range , Element Highest Point of Operation : Element Highest Point of Operation



Picnic Tables : At least 5% not Accessible

# Reach Ranges - Exterior : Reach Range , Clear Floor Space Slope

Main Entrance Door Switch - Switch

### Finding

The clear floor space slope is not compliant.

**On-Site Finding** 3.70 percent

### Recommendation

Provide compliant clear floor space.

Recommendation Up to 2.08 percent

# Costing Info (Estimated)

Redesign space\$2,200Code ReferenceADA 304,CA 11B-305.2

Record Number 168080

Reach Range , Clear Floor Space Slope  $\ : \ Clear$  Floor Space Slope





Library

# 440 W Sierra Madre Boulevard Sierra Madre, CA 91024

Date of Inspection 5/31/2016

# \*Estimated Facility Total: \$202,452

\*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

# **Disability Access Consultants**

(800) 743-7067

